SM2263XT+YMTC TAS FW & ISP Release Information – PKGU0806A_FWU0806A

Introduction

This purpose of this document is to provide release information on the SM22X family F/W and ISP release information

Fix Coverage

■ stands for the **"new fix"** or **"new support"** in the category
□ stands for the **"no-update"** in the category

□ **MP Tool**	■ **Controller ISP**
□ **Yield Issue** □ **Flash Issue** □ 3D Flash □ Samsung Flash □ Toshiba/Sandisk Flash □ Intel/Micron Flash □ Hynix Flash □ YMTC □ **MP Tool Bug Fix** □ **MP Tool New Function** □ **Feature Enhance**	□ **Yield Issue** □ **Flash Issue** □ 3D Flash □ Samsung Flash □ Kioxia/WD Flash □ Intel/Micron Flash □ Hynix Flash □ YMTC □ **ISP Bug Fix** ■ **Feature Enhance**

ISP Revision History

Package Version	ISP Version	MPTool Version	RDT Version	Note
U0806A	U0806A	U0804A	U0617ARD	1. MPISP was updated to fix 2lun NAND tranAdj issue 2. Retry function was adjusted to improve the performance after a high-temp retention test
U0701A	U0630A	U0624A	U0617ARD	Fixed a FFU function bug
U0618A	U0618A	U0609A	U0617ARD	SM2263XT FW first formal release to support YMTC TAS in the configuration of 4ch and 2ch.

Note:

1. F/W and ISP update is recommended.
2. History # is denoted by “Version-Date”.

This document is for information only and is subject to change without notice. Silicon Motion, Inc. reserves the right to make changes in the product design without reservation and without notice to its users.